



Customer Support Services
PARTS MANUAL
Tev 30 Jul 2008

Miscellaneous	3
Console Support and Deadshaft Covers	4
Handlebars and Bullhorns	5
Console and Related Components	6
Upper Frame Hardware	7
Rocker Arms and Pedal Levers	8
Crank Cover and Lower Caps	9
Lower Frame Shrouds and Hardware	10
Pedal Lever Components	11
PCB, Battery, Reed Switch, and Bracket	12
Bearing Insert Assembly	13
Crankarm Pulley Assembly	14
Drive Module	15
Drive Module Hardware	16
Cables	17

Description	Part No.
OPERATION MANUAL	M051-00K62-A111
SERVICE MANUAL	M051-00K62-A149
TOUCH UP PAINT:	
SPRAY CAN	0017-00008-0204
0.5 OZ BOTTLE W/APPLICATOR	0017-00008-0205
0.33 OZ PEN	0017-00008-0206
HARDWARE BAG	AK62-00152-0001
PLUG IN OPTION 120/60	GK62-00002-0018
PLUG IN OPTION 240/50 UK	GK62-00002-0019
PLUG IN OPTION 240v AUS	GK62-00002-0020
PLUG IN OPTION 230/50 CONT.	GK62-00002-0021
C-SAFE KIT	GK63-00002-0003


Model 93X has telemetry only.






NOTE: The Right Bullhorn Assembly consists of: AK62-00057-0001 Bullhorn, 0K62-01136-0000 Grip, and 0K62-01199-0000 Gasket.

NOTE: The Left Bullhorn Assembly consists of: AK62-00058-0001 Bullhorn, 0K62-01136-0000 Grip and 0K62-01199-0000 Gasket



CONSOLE	OVERLAY/BEZEL/SWITCH	LANGUAGE
AK62-00327-0001	AK62-00190-0001	Eng
AK62-00327-0003	AK62-00190-0003	Ger/Met
AK62-00327-0004	AK62-00190-0004	Spn/Met
AK62-00327-0006	AK62-00190-0006	Jap/Met
AK62-00327-0007	AK62-00190-0007	Frn/Met
AK62-00327-0008	AK62-00190-0008	Ital/Met
AK62-00327-0009	AK62-00190-0009	Dut/Met
AK62-00327-0010	AK62-00190-0010	Port/Met
AK62-00327-0014	AK62-00190-0010	Turk/Met


Items Not Shown	
Accessory Tray	0K62-01022-0000
Accessory Tray Mounting Screws (2)	0017-00101-1846





Rocker Arms Kit GK62-00002-0070 contents:


> Rocker Arms (2) Hardened Spacers (2) Oilite Washers (2) Retaining Rings (2) *Loctite 620* Alcohol pad

Rocker Arms AK62-00002-0070 Shaft Collar w/Screws 0K61-01259-0000










Note: If replacing the Tie Rod Assembly or Crank Extension for the first time, order kit GK62-00002-0015. Both sides must be replaced simultaneously in this situation.



this bearing insert assembly is used four times on this cross-trainer

Service Kit-MGK62-00002-0044 Includes:

- 1- crankshaft
- 2- bearings
- 2- sets of bearing flanges4- nuts and washers

Service Kit- GK62-00002-0045 Includes:

- 1 intermediate shaft
- 2 bearings
- 2- sets of bearing flanges
- 4- nuts and washers

